

Ki Pro Ultra Release Notes – v3.0

Firmware update for Ki Pro Ultra v3.0

Introduction

This firmware update is a major new feature release for Ki Pro Ultra. Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of www.aja.com.

New Features

Avid DNxHR MXF support has been added for the following profiles:

- Avid DNxHR HQX up to 4K/29.97 fps
- Avid DNxHR SQ up to 4K/29.97 fps
- Avid DNxHR LB up to 4K/29.97 fps

Enhancements

Minor bug fixes and various improvements have been made, including:

- Closed Caption support has been improved
- Improved large volume support for Pak 1000 and Pak 2000 media

Firmware Update Considerations

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.

- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com Phone: +1-530-271-3190 Fax: +1-530-274-9442

Web: www.aja.com/support Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA